

M/Y Meridian

Job report

2026-09-11 · Record #19258 · Generated by Ship's Log V1.5.19

Interior

Guest cabin 3 blackout blind motor — not retracting

[Open](#) · [Record #19258](#) · [logged 15:19](#) by [Captain](#)

Blackout blind motor in guest cabin 3 hums but won't retract fully. Likely the motor or limit switch. Flagged for the Chief Officer.