

M/Y Meridian

Job report

2026-09-11 · Record #19248 · Generated by Ship's Log V1.5.19

Engineering

Watermaker No.1 membrane service — flow restored

Completed · Record #19248 · logged 15:19 by Captain

Product flow had dropped to ~1,150 gph. Cleaned membranes with the acid/alkaline kit and renewed the pre-filters. Flow back to 1,760 gph, salinity 320 ppm.