

M/Y Meridian

Job report

2026-09-11 · Record #19254 · Generated by Ship's Log V1.5.19

Deck

Williams tender bilge pump fault — part on order

[Open](#) · [Record #19254](#) · [logged 15:19](#) by [Captain](#)

Williams auto bilge pump not cycling. Traced to a failed float switch; replacement on order from the Williams agent.